

Pick for offshore

Work Order ID 140361

140361

Page 1

Tuesday, December 22, 2015 4:08:31 PM

Item ID: D139-799-015

Accept

N900040100

Setup Start *NS1*

Revision ID:

Stop *NS2*

Item Name: Engine Wash

Start Date: 12/22/2015 Start Qty: 1.00

1

Cust Item ID:

Required Date: 1/7/2016 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals:

Process Plan:

Date: 6-1-8

Tooling:

Date:

Run Start *NR1*

QC:

Date:

SPC (Y/N):

Date:

Stop *NR2*

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr

Revision Nbr

IIN-D139-799

K 16-02-01

100

Document Control

0.00

DAS
6
9-89

DAS
27
9-89

MCS 16-01-21

100

DC

Memo

0.00

Doc.Control -USB or Paperwork

Photocopy bluefile & type labels per PPP D139-799-015
CHG005

110

Pick Kit

0.00

110

Packaging

Memo

0.00

Packaging

DAS
6
9-89

JAN 21 2016

DAS
28
9-89

120

QC4- 100% Inspect kits for completeness

0.00

120

QC

Memo

0.00

Quality Control

DAS
27
9-89

JAN 20 2016

JAN 28 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
							Completed By		
							Lead hand / Supervisor Approval Verification		
							QC / QA Coordinator Approval		

Root Cause				FAULT CATEGORY			
Environment ☐		No Re-verification ☐		Pressure/Forced ☐		Temperature/Cure ☐	
Design ☐		Operator ☐		Bending ☐		Set-up ☐	
Doc/Data ☐		Offset/Setup ☐		Centre Not Concentric ☐		BOM/Route ☐	
Equip/Tooling ☐		Supplier ☐		Cracks ☐		Broken/Damage/Defect ☐	
Handling/Pre ☐		Training ☐		Crimp/Kink/Ripple/Wave ☐		Inspection Incomplete/Unqualified ☐	
Material ☐		Use for Testing ☐		Cuffs ☐		Contamination ☐	
Internal Transport ☐		Poor Information ☐		Crushing ☐		Countersink ☐	
Tribal Knowledge ☐		Rushing ☐		Heat Treat ☐		Cut Too Short ☐	
LOA ☐		Product Improvement ☐		Wave/Twist in Tube ☐		Instructions Incomplete/Unclear ☐	
Substation ☐		Process Improvement ☐		Marks/Chatter ☐		Drill Holes ☐	
Past Expiry Date ☐		Manufacturing Process ☐		OTHER : ☐			
Misidentified ☐		Past Due ☐					

Work Order ID 140361***140361***

Page 2

Tuesday, December 22, 2015 4:08:31 PM

Item ID: D139-799-015

Accept

N900040100Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Engine Wash

Start Date: 12/22/2015 Start Qty: 1.00

1

Cust Item ID:

Required Date: 1/7/2016 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start ***NR1***

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
130		0.00							
130									
Packaging	Memo	0.00							
Packaging	Identify and pack for shipping as per PPP D139-799-015								
	Location: <u>off shore</u>								
	PPP rev: _____								
140	QC21- Final Inspection - Work Order Release	0.00							
140									
QC	Memo	0.00							
Quality Control									

DAS 27 9-89
DAS 28 9-89
JAN 28 2016

MCS
JAN 28 2016

MCS
JAN 28 2016

DQA: _____ Date: _____

**WORK ORDER NON-CONFORMANCE / UPDATE**

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
		OTHER : ☐							

Picklist Print

Page 1

Tuesday, December 22, 2015 4:08:36 PM

Work Order ID: 140361

140361

Parent Item: D139-799-015

D139-799-015

Parent Item Name: Engine Wash

Start Date: 12/22/2015

Required Date: 1/7/2016

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP Rev:B 11.07.04 new issue DD verf:JLM IPP REV:B
AS PER ECN 11-598 11-06-05 JLM VERF BY:DD IPP Rev:C 11.09.27
PER CHG003 DD verf:EC IPP Rev:D 13.09.24 PER
CHG005/ECN13-579 DD verf:JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D4121-1 *D4121-1* Hose Assy		Manufactured	No			110	Each	8.0000	2 **	2 140523			68-6 9 SVC
DAS 27 9-89 <u>Location</u> FG 3 114101 1 132053 2 ST214 5 137293 1 139051 4 <u>Loc Qty</u> <u>Loc Code</u> 													
D4121-3 *D4121-3* Hose Assy		Manufactured	No			110	Each	6.0000	1 **	1			68-6 9 SVC
DAS 27 9-89 <u>Location</u> FG 1 91535 1 ST213 4 137268 4 ST214 1 129024 1 <u>Loc Qty</u> <u>Loc Code</u> 													

JAN 21 2016

DAS
28
9-89

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐						
Date :		Step #:		QTY Effective :				MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Root Cause		FAULT CATEGORY								
Environment ☐	☐	No Re-verification	☐	Pressure/Forced	☐	Temperature/Cure	☐	Power Loss/Surge	☐	Positioned Wrong
Design ☐	☐	Operator	☐	Bending	☐	Set-up	☐	Folio/Program	☐	Outside Dimensions
Doc/Data ☐	☐	Offset/Setup	☐	Centre Not Concentric	☐	BOM/Route	☐	Grain	☐	Over/Under tolerance
Equip/Tooling ☐	☐	Supplier	☐	Cracks	☐	Broken/Damage/Defect	☐	Weld	☐	Part Incorrect
Handling/Pre ☐	☐	Training	☐	Crimp/Kink/Ripple/Wave	☐	Inspection Incomplete/Unqualified	☐	Wrong Stock Pulled	☐	Part Lost/Missing
Material ☐	☐	Use for Testing	☐	Cuffs	☐	Contamination	☐	Out of Sequence	☐	Part Moved
Internal Transport ☐	☐	Poor Information	☐	Crushing	☐	Countersink	☐	Off-set	☐	Drawing
Tribal Knowledge ☐	☐	Rushing	☐	Heat Treat	☐	Cut Too Short	☐	Mislabeled	☐	Finish
LOA ☐	☐	Product Improvement	☐	Wave/Twist in Tube	☐	Instructions Incomplete/Unclear	☐	Fit/Function	☐	Misread
Substation ☐	☐	Process Improvement	☐	Marks/Chatter	☐	Drill Holes	☐	Misaligned/off center	☐	Turning Sequence
Past Expiry Date ☐	☐	Manufacturing Process								
Misidentified ☐	☐	Past Due	OTHER :							

Picklist Print

Tuesday, December 22, 2015 4:08:36 PM

Page 2

Work Order ID: 140361

140361

Parent Item: D139-799-015

D139-799-015

Parent Item Name: Engine Wash

Start Date: 12/22/2015

Required Date: 1/7/2016

Start Qty: 1.00

Required Qty: 1.00

D4121-5 Manufactured No

110 Each

6.0000

1 1

D4121-5

Hose Assy

DAS
27
9-89

Location

Loc Qty

Loc Code

ST213

4

137227

4

ST214

2

135513

2

**

DAS

6

9-89

DAS

28

9-89

D4131-041 Manufactured No

110 Each

1.0000

1 1

D4131-041

Manifold Assembly

DAS
27
9-89

Location

Loc Qty

Loc Code

ST085

1

137617

1

**

DAS

6

9-89

DAS

28

9-89

D4131-043 Manufactured No

110 Each

2.0000

1 1

D4131-043

Doubler Assembly

DAS
6
9-89

Location

Loc Qty

Loc Code

ST085

2

135217

2

**

DAS

28

9-89

DAS

28

9-89

D4146-1 Manufactured No

110 Each

11.0000

2 2

D4146-1

Fitting

DAS
27
9-89

Location

Loc Qty

Loc Code

ST085

11

137090

11

**

DAS

6

9-89

DAS

28

9-89

DAS
27
9-89

JAN 21 2016

Tuesday, December 22, 2015 4:08:36 PM

Shop Packet Print

Page 2

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QSI042) Approval	
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐				
		OTHER : ☐							

Picklist Print

Tuesday, December 22, 2015 4:08:36 PM

Page 3

Work Order ID: 140361

140361

Parent Item: D139-799-015

D139-799-015

Parent Item Name: Engine Wash

Start Date: 12/22/2015

Required Date: 1/7/2016

Start Qty: 1.00

Required Qty: 1.00

D4182-1 Manufactured No

110 Each 12.0000 2 2

D4182-1
Fitting, Quick Disconnect

****** **DAS**
6
9-89

Location	Loc Qty	Loc Code
ST089	12	
135715	8	
138966	4	

2

D4384-1 Manufactured No

110 Each 6.0000 1 1

D4384-1
Placard

****** **DAS** **DAS**
6 28
9-89 9-89

140782

Location	Loc Qty	Loc Code
FG	5	
80679	5	
ST095	1	
133324	1	

JAN 2 6 2016

AN526-1032R16 Purchased No

110 Each 50.0000 4 4

AN526-1032R16
Screw

****** **DAS** **DAS**
6 28
9-89 9-89

Location	Loc Qty	Loc Code
ST325A	49	
m133234	49	
ST326	1	
m130928	1	

4

AN832-61 Purchased No

110 Each 15.0000 2 2

AN832-61
Union

****** **DAS** **DAS**
6 28
9-89 9-89

JAN 2 1 2016

Location	Loc Qty	Loc Code
CCK06	8	
m133234	8	
ST332	7	
m133031	7	

2

Tuesday, December 22, 2015 4:08:36 PM

Shop Packet Print

Page 3

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QS1042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
		OTHER : ☐							

Picklist Print

Tuesday, December 22, 2015 4:08:36 PM

Page 4

Work Order ID: 140361

140361

Parent Item: D139-799-015

D139-799-015

Parent Item Name: Engine Wash

Start Date: 12/22/2015

Required Date: 1/7/2016

Start Qty: 1.00

Required Qty: 1.00

AN924-6J

Purchased

No

110

Each

31.0000

4 4

AN924-6J

NUT

**

DAS

6

9-89

DAS

28

9-89

Location

Loc Qty

Loc Code

CCK06

12

m133234

12

FG

4

123245

2

m132256

2

ST322

15

m133686

15

MS21919-WDG9

Purchased

No

Each

122.0000

20

MS21919-WDG9

Clamp

**

DAS

6

9-89

DAS

28

9-89

Location

Loc Qty

Loc Code

CCK06

100

m133234

100

ST293

22

m133031

22

NAS1149C0932R

Purchased

No

110

Each

27.0000

4 4

NAS1149C0932R

WASHER

**

DAS

6

9-89

DAS

28

9-89

Location

Loc Qty

Loc Code

ST271

27

m131026

27

JAN 21 2016

DAS

27

9-89

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
		OTHER : ☐							

5.0 PARTS LIST

Qty -011	Qty -012	Qty -015	Qty -017	Qty -019	Qty -112	Qty -211	Qty -212	Qty -213	Part Number	Description
X									D139-799-011	MAINTENANCE STEP KIT, LH
	X								D139-799-012	MAINTENANCE STEP KIT, RH
		X							D139-799-015	ENGINE WASH KIT
			X						D139-799-017	CARGO FLOOR PROTECTOR KIT
				X					D139-799-019	CABIN FLOOR PROTECTOR KIT
					X				D139-799-112	MAINTENANCE STEP WITH GRAB BAR KIT, RH
						X			D139-799-211	QUICK RELEASE MAINTENANCE STEP KIT, LH
							X		D139-799-212	QUICK RELEASE MAINTENANCE STEP KIT, RH
								X	D139-799-213	QUICK RELEASE MAINTENANCE STEP PROVISIONS KIT
			2						D3580-1	JOGGLE BRACKET
			2	8					D3628-1	CUPPED WASHER
1									D4092-041	MAINTENANCE STEP ASSEMBLY
	1								D4092-042	MAINTENANCE STEP ASSEMBLY
		2							D4121-1	HOSE ASSEMBLY
		1							D4121-3	HOSE ASSEMBLY
		1							D4121-5	HOSE ASSEMBLY
				1					D4130-1	FWD CABIN FLOOR PROTECTOR
				1					D4130-3	AFT CABIN FLOOR PROTECTOR
			1						D4130-5	FWD CARGO FLOOR PROTECTOR
			1						D4130-7	CENTER CARGO FLOOR PROTECTOR
			1						D4130-9	AFT CARGO FLOOR PROTECTOR
		1							D4131-041	MANIFOLD ASSEMBLY
		1							D4131-043	DOUBLER ASSEMBLY
		2							D4146-1	FITTING
			1						D4153-1	JOGGLE BRACKET
			1						D4153-3	JOGGLE BRACKET
				4					D4153-5	CLAMP PLATE
			2						D4166-1	PLACARD, MAX LOAD
		2							D4182-1	FITTING, QUICK DISCONNECT
		1							D4384-1	PLACARD
					1				D4526-042	MAINTENANCE STEP ASSEMBLY, RH
						1			D5238-041	MAINTENANCE STEP ASSEMBLY
							1		D5238-042	MAINTENANCE STEP ASSEMBLY
						1	1	1	D5238-043	LOWER BRACKET, AFT
						1	1	1	D5238-045	LOWER BRACKET, FWD
						1	1	1	D5245-1	MOUNTING BOLT
2	2				2	2	2	2	AN6H12A	BOLT
2	2				2	1	1	1	AN6H13A	BOLT
		4							AN526-1032R16	SCREW
		2							AN832-03	UNION
		4							AN924-03	NUT
		20							MS21919WDG09	CLAMP
6	6				6	5	5	5	NAS1149D0663J	WASHER (or AN960JD616)
		4							NAS1149C0932R	WASHER (or AN960C916L)